Signed 10-17-17

INDUSTRIAL STORMWATER MONTHLY INSPECTION REPORT

Inspections must be conducted by a person with the knowledge and skills to assess conditions and activities that could impact stormwater quality at the facility, and evaluate the effectiveness of best management practices required by this permit. Retain a copy of the completed and signed form in accordance with Permit Condition S9.C.

FACILITY NAME: Alaskan Copper Works		INS	SPE	CTION TIME:	10:00 am	DATE: 10/16/17	
WEATHER INFORMATION:							
Description of Weather Conditions (e.g., sunny, cloudy, raining, snowing, etc.): Overcast, calm, about 55 degrees							
Was stormwater (e.g., runoff from rain or snowmelt) flowing at o inspection: Yes ⊠ No □ Comments:	utfal	ls an	d/or	discharge areas s	hown on the S	Site Map during the	
I. POTENTIAL POLLUTANT SOURCE AREA INSPECTION AN	D B	EST	MA	NAGEMENT P	RACTICES	EVALUATION	
SWPPP and Site Map: Have a copy of the SWPPP and site map with you during the inspection so that you can ensure they are current and accurate. Use it as an aide in recording the location of any issues you identify during the inspection.	Ye	No	De rer	ndings and Remoscribe any finding medial action combined date completed	gs below and pletion include	the schedule for ling the date initiated	
Is the Site Map current and accurate?	X	1	-Ir	nplementing nev	nection forms		
 Is the SWPPP inventory of activities, materials and products current? 	Х		-Implementing new monthly inspection f			pection for ms	
Any new potential pollutant sources must be added to the map and reflected in the SWPPP Facility Assessment & Tables 2, 2A, 3 and 5.							
Vehicle/Equipment Areas:	Yes	No	NA			ion	
Equipment cleaning: Check NA if not performed on-site. Skip section.				Documentation	a:		
Is equipment washed and/or cleaned only in designated areas?							
 Observe washing: Is all wash water captured and properly disposed of? 			х	- No washing o	bserved at th	e facility.	
Equipment fueling: Check NA if not performed on-site. Skip section.							
 Are all fueling areas free of contaminant buildup and evidence of chronic leaks/spills? 	X		-Fueling areas in good condition			ition	
 Are all chemical liquids, fluids, and petroleum products, on an impervious surface that is surrounded with a containment berm or dike that is capable of containing 10% of the total enclosed tank volume or 110% of the volume contained in the largest tank, whichever is greater? 	х			- Drums stored	in connex bo	ox with berm	
 Are structures in place to prevent precipitation from accumulating in containment areas? 	х			- Diesel tank no and concrete co		it has double wall	
 If not, is there any water or other fluids accumulated within the containment area? 							
 Note: If containment areas are not covered to prevent water from accumulating, the SWPPP must include a plan describing how accumulated water will be managed and disposed of. 							

Equipment maintenance:	Yes	No	NA	
 Are maintenance tools, equipment and materials stored under shelter, elevated and covered? 	x			Documentation:
 Are all drums and containers of fluids stored with proper cover and containment? 	X			
 Are exteriors of containers kept outside free of deposits? 	X			
 Are any vehicles and/or equipment leaking fluids? Identify leaking equipment. 		х		
 Is there evidence of leaks or spills since last inspection? Identify and address. 	х			-3317 Tennant has forklift with evidence of leak. Kitty litter under needs to be cleaned
Are materials, equipment, and activities located so that leaks are contained in existing containment and diversion systems (confine the storage of leaky or leak-prone vehicles and equipment awaiting maintenance to protected areas)?	x			today. Move forklift indoors. 10-17 ROD FINION Chennard, HAS offered to move the
Add any additional site-specific BMPs:				FINEL: Jof And Closuffice Arusa. Corl Vinke
				ATMA. CARI VINKE
		l		

I. POTENTIAL POLLUTANT SOURCE AREA INSPECTION AND BEST MANAGEMENT PRACTICES EVALUATION							
Good Housekeeping BMPs:	Yes	No	NA	Findings and Remedial Action			
1. Are paved surfaces free of accumulated dust/sediment and debris?	İ			Documentation:			
Date of last quarterly vacuum/sweep 9/16/17	X						
 Are there areas of erosion or sediment/dust sources that discharge to storm drains? 	Х			- Pothole in front of 3200 has recently had rock placed to fill hole. R&R of pavement			
2. Are all waste receptacles located outdoors:				scheduled to be completed by mid Nov.			
In good condition?	X						
Not leaking contaminants?	X						
 Closed when is not being accessed? 	X			- Multiple receptacles throughout facility. All			
• External surfaces and area free of excessive contaminant buildup?	X			closed (except wood bin). A small container near 3405 with metal in it needs to be moved			
3. Are the following areas free of accumulated dust/sediment, debris, contaminants, and/or spills/leaks of fluids?				indoors.			
External dock areas	X						
Pallet, bin, and drum storage areas	X			:			
 Maintenance shop(s) 	Х						
• Equipment staging areas (loaders, tractors, trailers, forklifts, etc)	x						
 Around bag-house(s) 			x				
 Around bone yards 	$ _{X} $		^				
Other areas of industrial activity:	X						
	^			-Pavement appears to be regularly swept and free of debris and buildup.			
				nee of debris and bundup.			
				-3300 building tenant needs to address outdoor storage adjacent to DP-7 basin.			
		4	\downarrow	→			

			т	
Spill Response and Equipment:	Yes	No	NA	Findings and Remedial Action Documentation:
Are spill kits available, in the following locations?				Documentation:
Fueling stations	X		ļ	
Transfer and mobile fueling units	X			
Vehicle and equipment maintenance areas	X			
Do the spill kits contain all the permit required items?			ļ	
Oil absorbents capable of absorbing 15 gallons of fuel.	$ _{X}$			
A storm drain plug or cover kit.	x			
A non-water containment boom, a minimum of 10 feet in length with a 12 gallon absorbent capacity.	x			
A non-metallic shovel.	X			
Two five-gallon buckets with lids.	X			
Are contaminated absorbent materials properly disposed of?	x			
I. POTENTIAL POLLUTANT SOURCE AREA INSPECTION AN	annest terrological	200000000000000000000000000000000000000	000000000000000000000000000000000000000	
General Material Storage Areas:	Yes	No	NA	Findings and Remedial Action Documentation:
 Are damaged materials stored inside a building or another type of storm resistance shelter? 	x			Documentation.
 Are all uncontained material piles stored in a manner that does not allow discharge of impacted stormwater? 			X	-One scrap metal bin near 3405 needs to be
Are scrap metal bins covered?	X			moved indoors or covered. All other bins
Are outdoor containers covered?	Х			covered.
Stormwater BMPs and Treatment Structures: Visually inspect all	Yes	No	NA	Findings and Remedial Action
stormwater BMPs and treatment structures devices, discharge areas infiltration and outfalls shown on the Site Map.				Documentation:
 Are BMPs and treatment structures in good repair and operational? 	x			Danman and Eldama will be seen in
 Are BMPs and treatment structures free from debris buildup that may impair function? 	x			- Downspout filters will be monitored next month to determine maintenance.
• The permit requires Permittees to clean catch basins when the depth of debris reaches 60% of the sump depth. In addition, the Permittee must keep the debris surface at least 6 inches below the outlet pipe. Based on this, do catch basins need to be cleaned?		x		-CBs were cleaned in May
Are berms, curbing or other methods used to divert and direct discharges adequate and in good condition?	x			-Additional berming near 3300 tenant building may be needed. Will be evaluated next rain.
Observation of Stormwater Discharges:	Yes	No	NA	Findings and Remedial Action
 Is the discharge free of floating materials, visible oil sheen, discoloration, turbidity, odor, foam or any other signs of contamination? 			x	Documentation:
Water from washing vehicles or equipment, steam cleaning and/or pressure washing is considered process wastewater and is not allowed to comingle with stormwater or enter storm drains. Is process water comingling with stormwater or entering storm drains?		x		
 Illicit discharges include domestic wastewater, noncontact cooling water, or process wastewater (including leachate). Were any illicit discharges observed during the inspection? 		x		

II. CORRECTIVE ACTION AND and corrective actions if needed. Prov	SWPPP MODIFICATIONS DESCRIPTIONS DESCRIPTION	PTIONS: Additional space to describe ion and the rationale for the additional c	inspection findings or different BMPs.
Move forklift near 3317 building	ng by 10/17/17		
Move scrap metal bin near build	- -		
I fortaliff moved	10-17-17 April Chame	dup, CorlVink	E.
2 Berap metal b	in movEd INDOORS	, /	
III. CERTIFICATION STATEMEN	NTS AND SIGNATURES:		
Inspector - Certification: This section	n must be completed by the person who	conducted the site inspection prior to su	bmitting this form
	(see Permit Condition G2) or a duly auth	•	
The facility is in compliance with t	the terms and conditions of the SWPPP a	and the Industrial Stormwater General Pe	ermit.
The facility is out of compliance w report includes the remedial action implementation of the remedial act	with the terms and conditions of the SWP. Is that must be taken to meet the requirent tions.	PP and the Industrial Stormwater Generates of the SWPPP and permit, including	al Permit. This ag a schedule of
"I certify that this report is true, accur	rate, and complete, to the best of my know	wledge and belief."	
Chad Wiggins	Chad Wiggi	Water Resources Engineer	10/16/17
Inspector's Name – Printed	Inspector's Signature	Inspector's Title	Date
Permittee – Certification:			
The facility is in compliance with t	he terms and conditions of the SWPPP a	nd the Industrial Stormwater General Pe	rmit.
☐ The facility is out of compliance w	ith the terms and conditions of the SWPls that must be taken to meet the requirem	PP and the Industrial Stormwater Genera	ıl Permit. This
accordance with a system designed Based on my inquiry of the person of information, the information submit	t this document and all attachments were to assure that qualified personnel prope or persons who manage the system, or th tted is, to the best of my knowledge and l ting false information, including the poss	rly gathered and evaluated the informat ose persons directly responsible for gati belief, true, accurate, and complete. I an	ion submitted. hering 1 aware that there
CATI VIYLE	Come Vinte		0-17-17
PRINTED NAME of person with Signature Authority (permit condition G2.A) or a De Authorized Representative!			ATE
G2.A and submitted to Ecology, and 2) operation of the regulated <i>facility</i> , such	ative only if 1) the authorization is made the authorization specifies either an ind as the position of plant manager, supering sponsibility for environmental matters	ividual or a position having responsibilit	y for the overall